

## ”how to do” 3D STAR bottom surface

### **We have following advice:**

1. Clean the surface. (you can use G6 rubbing compound)
2. If the bottom have deep scratches you have to apply some gelcoat\*
3. If the bottom have small scratches – then
4. Sand the area or the entire bottom with sandpaper (dry 220)
5. Clean the bottom for dust
6. Wax the area with a thin vax (Teflon or Silicon)

.

\*See the “how to do” **FIX SCRATCHES**